

DOCUMENT RESUME

ED 109 477

CE 004 335

AUTHOR Kagan, Alfred; And Others
 TITLE Drill Press Operator: Instructor's Guide.
 INSTITUTION New York State Education Dept., Albany. Bureau of Continuing Education Curriculum Development.; New York State Education Dept., Albany. Bureau of Secondary Curriculum Development.
 PUB DATE 75
 NOTE 85p.; Part of Single-Tool Skills Program, Machine Industries Occupations
 EDRS PRICE MF-\$0.76 HC-\$4.43 PLUS POSTAGE
 DESCRIPTORS Adult Education; *Curriculum Guides; Machine Tool Operators; *Machine Tools; Metal Working Occupations; Post Secondary Education; Secondary Education; Shop Curriculum; *Trade and Industrial Education
 IDENTIFIERS *Drill Press Operators

ABSTRACT

The course is intended to help meet, in a relatively short time, the need for trained operators in metalworking. It can be used by students with little education or experience and is suitable for use in adult education programs and in manpower development and training programs. The course is designed to be completed in approximately 30 weeks and can be adapted for use in secondary schools. On successful completion of the course the student will be qualified for an entry-level job as operator in a drill press; he will not qualify as a machinist. The guide includes a general job content outline for the teacher to use in explaining what the operator's job includes. There are 11 shop projects (comprising 19 jobs) accompanied by 32 pages of drawings for the projects. Three of the jobs introduce students to the use of metric measurement. For each job there is a job sheet providing details on performance objectives, equipment, operations, materials, references, procedure, techniques, and time required. (Author/PR)

 * Documents acquired by ERIC include many informal unpublished *
 * materials not available from other sources. ERIC makes every effort *
 * to obtain the best copy available. nevertheless, items of marginal *
 * reproducibility are often encountered and this affects the quality *
 * of the microfiche and hardcopy reproductions ERIC makes available *
 * via the ERIC Document Reproduction Service (EDRS). EDRS is not *
 * responsible for the quality of the original document. Reproductions *
 * supplied by EDRS are the best that can be made from the original. *

Machine Industries Occupations

INSTRUCTOR'S GUIDE FOR AN ADULT COURSE



DRILL PRESS OPERATOR

JUN 06 1975

PART OF
SINGLE-TOOL SKILLS
PROGRAM SERIES

U.S. DEPARTMENT OF HEALTH,
EDUCATION & WELFARE
NATIONAL INSTITUTE OF
EDUCATION
THIS DOCUMENT HAS BEEN REPRO-
DUCED EXACTLY AS RECEIVED FROM
THE PERSON OR ORGANIZATION ORIGIN-
ATING IT. POINTS OF VIEW OR OPINIONS
STATED DO NOT NECESSARILY REPRESENT
THE NATIONAL INSTITUTE OF
EDUCATION. OCS 19 POL. CY

ED109477

CE004335

Drill Press Operator

INSTRUCTOR'S GUIDE

Part of
SINGLE-TOOL SKILLS PROGRAM
MACHINE INDUSTRIES OCCUPATIONS



The University of the State of New York
THE STATE EDUCATION DEPARTMENT
Bureau of Continuing Education Curriculum Development
Bureau of Secondary Curriculum Development
Albany, New York 12234
1975

THE UNIVERSITY OF THE STATE OF NEW YORK

Regents of The University (with years when terms expire)

1984 Joseph W. McGovern, A.B., J.D., L.H.D., LL.D., D.C.L.,
Litt.D., Chancellor - - - - - New York
1981 Theodore M. Black, A.B., Litt.D., LL.D., Pd.D.,
Vice Chancellor - - - - - Sands Point
1978 Alexander J. Allan, Jr., LL.D., Litt.D. - - - - - Troy
1987 Carl H. Pforzheimer, Jr., A.B., M.B.A., D.C.S.,
H.H.D. - - - - - Purchase
1975 Edward M. M. Warburg, B.S., L.H.D. - - - - - New York
1980 Joseph T. King, LL.B. - - - - - Shelter Island
1981 Joseph C. Indelicato, M.D. - - - - - Brooklyn
1976 Helen B. Power, A.B., Litt.D., L.H.D., LL.D. - - - - - Rochester
1979 Francis W. McGinley, B.S., J.D., LL.D. - - - - - Glens Falls
1986 Kenneth B. Clark, A.B., M.S., Ph.D., LL.D., L.H.D.,
D.Sc. - - - - - Hastings on
Hudson
1983 Harold E. Newcomb, B.A. - - - - - Owego
1988 Willard A. Genrich, LL.B., L.H.D. - - - - - Buffalo
1982 Emlyn I. Griffith, A.B., J.D. - - - - - Rome
1977 Genevieve S. Klein, B.S., M.A. - - - - - Bayside
1981 William Jovanovich, A.B., LL.D., Litt.D., L.H.D. - - - - - Briarcliff
Manor

President of The University and Commissioner of Education
Ewald B. Nyquist

Executive Deputy Commissioner of Education
Gordon M. Ambach

Deputy Commissioner for Elementary, Secondary, and Continuing Education
Thomas D. Sheldon

Associate Commissioner for Instructional Services
William L. Bitner III

Assistant Commissioner for General Education and Curricular Services
Vivienne N. Anderson

Director, Division of Curriculum Development
Gordon E. Van Hooft

Chief, Bureau of Continuing Education Curriculum Development
Herbert Bothamley

Assistant Commissioner for Occupational and Continuing Education
Robert S. Seckendorf

Director, Division of Occupational Education Instruction
Robert H. Bielefeld

Chief, Bureau of Trade and Technical Education
Carl G. Benenati

Foreword

The *Drill Press Operator* course contained in this book is intended to help fill the need for people trained to operate machine tools. The backgrounds of those who enter the course will cover a broad range of qualifications, but it is likely that many people with little education or experience will be included. Completion of this course alone, obviously will not make anyone a full-fledged machinist.

This course is the fourth one to be published in a series of instructor's guides for the Single-Tool Skills Program. (*Engine Lathe Operator* was published in 1972, *Surface Grinder Operator* in 1973, and *Milling Machine Operator* in 1974.) Although written primarily as an adult course, the secondary level teacher can use the content of this book in a course he or she might develop for the students. *Drill Press Operator* was produced as a joint project of the two curriculum bureaus named on the title page.

The Single-Tool Skills Program is one of the programs in a broad plan covering machine industries occupations. The original plan was conceived by Robert S. Hunter, former associate in the Bureau of Trade and Technical Education. A number of teachers were involved in the overall planning for machine industries occupations and also wrote material for the course guides. They are Elek D. Csont, Seneca Vocational High School, Buffalo; Jack Grossman, Alexander Hamilton High School, Brooklyn; Alfred Kagan, Sewanhaka High School, Floral Park; Gilbert Pultz, Jefferson Vocational and Technical Center, Watertown; William G. Stewart, North Senior High School, Binghamton; William F. Tiedemann, Central Technical High School, Syracuse; and Joseph Waldinsperger, College of Continuing Education, Rochester Institute of Technology, Rochester.

Other members of the State Education Department took part in the overall planning and in the further detailed planning which resulted in the production of this publication. They are E. Noah Gould, associate in the Bureau of Continuing Curriculum; G. Earl Hay, supervisor in the Bureau of Secondary Curriculum; Edward Shattuck, former associate in the Bureau of Trade and Technical Education; and Charles A. Stebbins, associate in the last-named bureau.

Messrs. Kagan, Stewart, and Tiedemann wrote the *Drill Press Operator* course contained in this book. Most of the drawings in this guide are taken from previous publications in the series. The additional drawings needed and changes in old drawings were made by Eugene F. Stalica, Jr., professor at Hudson Valley Community College, Troy. Mr. Gould, who is in general charge of the Single-Tool Skills series, directly supervised the writing and edited the manuscript.

HERBERT BOTHAMLEY, *Chief*
Bureau of Continuing Education
Curriculum Development

GORDON E. VAN HOOFT, *Director*
Division of Curriculum Development

Message to the Instructor

This *Drill Press Operator* course is expected to help meet the need for trained operators in metalworking. The course is suitable for use in the adult education programs of school districts, and in Manpower Development and Training programs. It can also be adapted for use in secondary schools.

Anyone who completes this course successfully will be qualified for an entry-level job as operator of a drill press. Some students may also complete other single-tool courses and qualify to operate more than one machine tool. It is even possible that a student with outstanding ability, by completing the courses for several machine tools, could become a machinist.

The 11 projects in this course (which include 19 shop jobs) are listed on the page after *Contents*. There is no requirement that any student complete all projects, or even all jobs within any project. The instructor may determine which projects and jobs a given student should complete and whether to have him use conventional or metric dimensions. The instructor may also use other jobs not included in this book.

The teacher for this course would ideally be a person with not only good training and experience in machinist skills, but also several years of teaching experience. The best sources from which to draw teachers are the faculties of schools giving machine tool courses and the ranks of those employed as machinists and supervisors of machinists.

An administrator or instructor who has any questions or comments about this publication should direct them to either the Bureau of Trade and Technical Education or to one of the bureaus named on the title page.

CARL G. BENENATI, *Chief*
Bureau of Trade and
Technical Education

ROBERT H. BIELEFELD, *Director*
Division of Occupational Education Instruction

Contents

	Page
Foreword	iii
Message to the Instructor	iv
List of Shop Projects	vi
List of Drawings for Shop Projects	vii
INTRODUCTION	1
GENERAL JOB CONTENT	5
JOB SHEETS FOR SHOP PROJECTS	10
BIBLIOGRAPHY	43
DRAWINGS FOR SHOP PROJECTS	44

MACHINE INDUSTRIES OCCUPATIONS
SINGLE-TOOL SKILLS PROGRAM
DRILL PRESS OPERATOR COURSE

LIST OF SHOP PROJECTS

<u>Project No.</u>	<u>Time (hrs.)</u>	<u>Page</u>
I. Drill Stand		
Job 1. Drill Stand	9	11
II. Parallel Clamp		13
Job 1A. Loose Jaw (inches)	4	
Job 1B. Loose Jaw (millimeters)	4	
Job 2. Threaded Jaw (inches)	3	
III. Parallels		19
Job 1A. Parallels (inches)	6	
Job 1B. Parallels (millimeters)	6	
IV. Bench Vise		23
Job 1. Screw	$1\frac{1}{2}$	
Job 2. Fixed and Movable Jaws	3	
V. Arbor Press		27
Job 1. Base	3	
VI. Tap Wrench		29
Job 1. Tap Wrench Body	$1\frac{1}{2}$	
VII. 1-2-3 Block		30
Job 1. 1-2-3 Block (Dual Dimensioning)	5	
VIII. Micrometer Boring Head		32
Job 1. Dovetail Blocks	$2\frac{1}{2}$	
IX. Precision Step Block		34
Job 1. Precision Step Block	$2\frac{1}{2}$	
X. Motor Plate		36
Job 1. A, B, and C Holes	2	
Job 2. D Holes	$1\frac{1}{2}$	
Job 3. E Holes	2	
Job 4. F and G Holes	3	
Job 5. H Hole	2	
XI. Close Quarters Hacksaw		42
Job 1. Adjustable Blade Retainer	$\frac{1}{2}$	

MACHINE INDUSTRIES OCCUPATIONS
SINGLE-TOOL SKILLS PROGRAM
DRILL PRESS OPERATOR COURSE

LIST OF DRAWINGS FOR SHOP PROJECTS

Dwg. No.	Title of Drawing	Project	Drill Press Jobs Covered	Page
13	Close Quarters Hacksaw: Assembly	XI	1	45
14	Close Quarters Hacksaw: Details		1	46
15	Bench Vise Assembly	IV	1,2	47
16	Bench Vise Details		1	48
17	Bench Vise: Fixed and Movable Jaws		2	49
21	Tap Wrench	VI	1	50
22	Micrometer Boring Head: Assembly	VIII	1	51
22.1	Micrometer Boring Head: Plate		None	52
22.2	Micrometer Boring Head: Dovetail Blocks		1	53
23	Micrometer Boring Head: Dial, Shank, and Stop Pin		None	54
24	Micrometer Boring Head: Dovetail Slide		None	55
27	Arbor Press: Assembly	V	1	56
28	Arbor Press: Gear Shaft, Rack Pad, and Rack		None	57
29	Arbor Press: Table		None	58
30	Arbor Press: Sleeve, Table Pin, and Cover Plate		None	59
31	Arbor Press: Handle and End		None	60
32	Arbor Press: Column		None	61
33	Arbor Press: Base		1	62
42	Drill Stand	I	1	63
44	Precision Step Block	IX	1	64
45.1	1-2-3 Block (Dual Dimensioning)	VII	1	65
50A	Parallels (Inches)	III	1A	66
50B	Parallels (Millimeters)		1B	67
56	Parallel Clamp: Assembly	II	1A,1B,2	68
57A	Parallel Clamp: Loose Jaw (Inches)		1A	69
57B	Parallel Clamp: Loose Jaw (Millimeters)		1B	70
58A	Parallel Clamp: Threaded Jaw (Inches)		2	71
58B	Parallel Clamp: Threaded Jaw (Millimeters)		None	72
59	Parallel Clamp: Straight Clip		None	73
60	Parallel Clamp: Clamping Screw		None	74
61	Parallel Clamp: Adjusting Screw		None	75
72	Motor Plate	X	1,2,3,4,5	76

Introduction

As shown in the contents, this *Drill Press Operator* course consists of this Introduction, General Job Content (which explains what the operator's job includes), Job Sheets for projects, and the drawings for the projects. The course covers the operation of the drill press only.

Objectives of the Course

The job for which the trainee would be qualified upon completion of this course is referred to in the Dictionary of Occupational Titles (under the code number 606.380) as drill press operator; drill press operator, multiple spindle; drill press operator, radial; gang drill press operator. Other job titles are also used under this and other code numbers.

The general objective of the course is to train persons, in a relatively short time, to be placed as drill press operators. Another important purpose is to help those with very little background. The course is not intended to give a broad training in metalworking, but only the skill to operate one kind of metalworking machine. By keeping the objective narrow, the training time is kept to a minimum, and the trainees are made available for work without a long delay.

Units of Measurement

Generally speaking, conventional units of measurement (inches for linear dimensions, and degrees for angles) are used in this course. However, an attempt has been made to introduce the students to metric measurement by using millimeters for dimensions in several projects, in addition to the conventional units.

The United States is the only big country in the world which is not either using metric measurements or in a program for changing to metrics. Legislation is now pending in Congress which is likely to start us on a 10-year changeover period which would result in making metric units the predominant means of measurement. The much greater convenience of metric units and our increasing trade with countries on the metric system are the main forces pushing us toward metrication.

In American industry, some companies are already using metric measurements to a large extent in their products. Examples of such companies are the Beloit Tool Corporation of South Beloit, Illinois, and the Caterpillar Tractor Company of Peoria, Illinois. American metalworking companies using metric units are apparently continuing to use conventional thread

systems. This is because, according to some authorities, the conventional threads have some significant advantages over metric threads. References listed in the bibliography contain further information on metrics.

Metric Units in this Course

In this course, the workpieces for three shop jobs have been designed in both conventional and metric units. Job Sheets and drawings using both inches and millimeters are included so an instructor can have a student make these pieces in either conventional or metric dimensions or both. These jobs are:

<u>Project</u>	<u>Job</u>	
I	1A & 1B	Parallel Clamp Loose Jaw
II	2A & 2B	Parallel Clamp Threaded Jaw
III	1A & 1B	Parallels

In Projects II and III, Job 1A is in conventional units and Job 1B is in metric units. For these jobs, the only additional instruments suggested are a 15 cm. metric scale, a 0-25 mm. micrometer, and a metric dial indicator.

Drawings and Job Sheets

The drawings in this course are part of a serially numbered set beginning with No. 1, which appears in the *Engine Lathe Operator* course. The numbers continue through the drawings of other courses in the Single-Tool Skills Series including this one. They will be continued further in any other courses in the series which might be published later. Drawings in this course which are also in one of the other courses are reproduced here with the same drawing numbers. Some drawings appear in this book which are not needed for the shop projects of this course. They are included here for the convenience of keeping together all the drawings of an assembly. Those in this publication run from 13 through 62 of the series.

In the drawings, all dimensions are in inches unless otherwise indicated. A number of drawings contain tables giving several different sets of dimensions for the workpieces pictured. These tables permit the instructor to select the set of dimensions which he finds best for each student or for the conditions under which his class operates.

Each job sheet has the words *Unit No.* in the upper left corner, but no number is given. The instructor may wish to write a number in this space to fit in with his own method of organizing his classroom and shop work.

Assignment of Work to Students

As a shop project is assigned to a student, we recommend that the instructor give him copies of the applicable Job Sheets and drawings. The binding of this book permits easy removal of pages for copying. When copies are made the pages themselves must be kept clean and should not be used by

anyone working on a machine. After any copies are made the pages should be replaced in the book and the book should be kept in a looseleaf cover.

Each drawing has four blocks for information at the bottom and two of them are blank. We suggest that the instructor have the student write the numbers of the project and job for which he is using the drawing in one of these blank spaces on his own copy.

Many of the workpieces on which drilling is to be done in this course are those produced in other courses in the Single-Tool Skills series. If a given workpiece is not available as the output of another course in his shop, it is the instructor's responsibility to obtain the workpiece. In some cases, he may need to make it himself.

Administration of the Course

We believe that enough general information about the job and more than enough shop projects are included for the trainee to reach the general objective of the course. All essential drill press skills are used in the shop jobs a number of times.

The schools may use everything in the course, they may select only some of the material, they may make changes in it, and they may use other material not contained here. They may also determine the length of the class periods, their frequency, and the total amount of time to be spent in training. For those that need a guide: A typical adult night class runs $2\frac{1}{2}$ to 3 hours, either once or twice a week, for 30 weeks.

The prerequisites for admission to an adult course should be broad enough so none will be barred who could be made employable. The operating authorities for each program, school, and school district have the responsibility for determining the prerequisites for such a course, and can adapt them to any special local conditions.

The *minimum* prerequisites we suggest for a trainee (and they are not mandatory) are that he have enough ability to understand and follow the course instructions (both written and oral) so he can produce the simplest workpiece included in the course. Such a trainee will, perhaps, be able to qualify only as a production machine operator, where all the machine setups are made for him. Another trainee with more background will possibly qualify for jobs requiring more skill, such as drill press setup man.

The Job Sheets show two references which are especially recommended for drill press work. The bibliography gives the complete citations for these two books and also contains additional references.

Abbreviations used in this course are given on the next page.

Abbreviations Used in Text and Drawings

ALUM.	aluminum	HT.	height
ASSY.	assembly	LG.	long
CHAM.	chamfer	LGTH.	length
CBORE.	counterbore	MATL.	material
CM.	centimeter(s)	MED.	medium
CRS	cold rolled steel	MM.	millimeters
CSK.	countersink	PT.	part
DIA.	diameter	R or RAD.	radius
DP.	deep	REOD.	required
DP	diametral pitch	R.H.	right-hand
DR.	drill	SCR.	screw
DR or DR. ROD	drill rod	SOC.	socket
EQ. SP.	equally spaced	SPEC.	specifications
FAO	finish all over	SPHER.	spherical
IID	head	STL.	steel
HDL.	handle	SQ.	square
HGT.	height	TYP.	typical
HEX.	hexagonal	W.	width
H.S.	high-speed		

General Job Content

- I. Types of Machines Provide information on types and designs of drill presses, such as:
1. standard
 2. single-spindle sensitive
 3. radial
 4. gang
 5. multiple-spindle
- Point out that although treated as a category in itself, numerical control drilling follows the basic drilling theory and techniques. Numerically controlled drilling differs from basic drilling technique in that it uses a preprogrammed data system to position and feed the drills.
- II. Machine Parts Point out and name the drill press parts: base, column, and table.
- III. Machine Accessories
- A. Toolholding Establish familiarity with drill press toolholding devices. Some of these include: sockets, sleeves, and drill chucks.
- B. Work holding Discuss work holding devices, such as: vises, jigs, and clamps.
- IV. Cutting Tools Describe the various types of cutting tools used: drills, machine reamers, hand reamers, counterbores, step drills, and countersinks.
- Identify the various parts of the cutting tools. Some parts of the drill are: body, shank, neck, tang, point, and web.
- Explain the procedures followed in grinding and sharpening the various cutting tools.
- V. Measurement and Inspection List and explain the various types of measuring tools. These could include: micrometer, indicator, plug gages, and thread plug gages.
- VI. Blueprint Reading Introduce and cover all necessary blueprint reading, such as:

1. theory of orthographic projection
2. language of lines
3. sectional views
4. tolerances

VII. Speeds and Feeds

The choice of speed and feed depends on:

1. composition and hardness of work material
2. cutting fluid efficiency
3. type and condition of machine
4. quality of finish required

Explain how to use the formula for calculating the speed of a drill. For example:

$$\text{RPM} = \frac{4 \times \text{cutting speed}}{\text{dia. of drill}}$$

Explain how to read and use tap drill charts.

Make available charts and tables which will enable the student to select proper speeds and feeds for hand or automatic operations.

Demonstrate how the diameter of the drill, the material being machined, the nature of the toolholders, and the finish required all correlate with the proper choice of speeds and feeds.

VIII. Trade Mathematics

Introduce and cover all necessary trade mathematics, such as basic arithmetic, use of constants, and use of formulas.

IX. Coolants

Develop an understanding of coolants, including:

1. water base type
2. oil type
3. chemically active sulphur-fatty type
4. sulphur-mineral oils

Give examples of particular drilling conditions and the kind of coolant to use. Explain how the proper coolant can increase tool life, give a better finish, and help maintain close hole tolerance.

X. Care and Maintenance

Provide information concerning the care and maintenance of the various types of drill presses, such as: wiping the spindle hole before inserting a tool and making sure the machine is properly oiled and cleaned.

XI. Safety

Introduce the following safe working practices for operating the machine:

1. Wear close fitting clothes.
2. Wear safety glass.

3. Make sure the guards are kept in place.
4. Keep hands away from moving parts.
5. Know how to operate the controls.

Discuss particular dangers to avoid when operating the machine, such as:

1. Never leave the chuck key in the chuck.
2. Never hold work with your hands. Clamp the workpiece securely with standard devices such as: a drill vise, straps, C clamps, parallel clamps, and stops.
3. Always use a brush to remove chips--never your hands or rags.
4. Keep your head away from the turning spindle to prevent hair entwining around it.
5. Never attempt to drill brass, copper, or bronze with a drill ground for steel. Demonstrate negative rake on the drill when drilling brass, copper, or bronze.
6. Ease up on the feed pressure as the drill begins to break through a hole.
7. Demonstrate the proper setup for drilling thin material including the holding device, the support, and the cutting tool.
8. Explain how the hand feed lever can injure the operator's face if he allows it to rotate uncontrolled while drilling to depth or when adjusting the column.

XII. Trade Terms

Explain all trade terms peculiar to the trade, such as press fit, pitch, jig, and flute.

XIII. Work Processes A. Drilling

Mention that drilling is a very important phase of the trade, and that it is performed on a wide range of equipment. For example: the sensitive drill press, and the heavy duty radial drill press.

Continue by explaining that drills are classified as: number drills, letter drills, millimeter drills, and fractional drills.

Explain that in center drilling a combination drill and countersink is used to locate a hole and prevents the drill from wandering. Exhibit various sizes of center drills and explain how each is selected in proportion to the size of the drilled hole.

Discuss ways to achieve particular finishes and tolerances.

Explain the causes of drill failure, some of which are: speed too high, feed too high, and drill sharpening not properly done.

- B. Boring Explain that boring is done to enlarge and/or true a hole.
- C. Counterboring Discuss how a counterboring tool is used to enlarge a hole to a given diameter and depth, in order that a nut or bolt head may set flush or below the surface.
- D. Countersinking Point out that countersinking makes a cone-shaped enlargement on the end of a hole in order that a flathead screw seats properly to a particular depth.
- E. Spot facing Add that spot facing is similar to counterboring except that it is used to produce a shallow machined area on cast or forged surfaces.
- F. Tapping Explain how tapping is done with a drill press using friction drive tapping heads.

Point out how the actual cutting by the tap is done by the chamfer and the first full thread of the tap.

Impress upon the class the importance of runout and tap alignment with the drilled hole. If these factors are not considered, then the threaded hole may not be square or the pitch diameter may be oversize. In extreme cases, these errors will result in broken taps.

Comment on some of the standard practices used in tapping:

1. Never tap through a hard bushing.
2. Countersink a hole before tapping.
3. Use spiral point or gun taps for through holes.

Direct attention to the importance of the tap and drill diameter and how it affects:

1. pitch diameter
2. depth of thread
3. amount of strain on the tap
4. quality of finish of the thread

Distribute material explaining the identification marking used on taps, for example:

$\frac{1}{2}$ -13 UNC

- G. Gun Drilling Describe the gun drill and its application. Point out that it is used on a machine designed especially for gun drilling.
- Explain why the cutting fluid must be run at high pressures for this kind of operation.
- H. Sub-land and Step Drilling Discuss the application of subland drills and step drills. Show how the design of the drill allows for the drilling of two or more diameters, or for the combination of a drilling operation with counterboring, countersinking, or reaming.
- I. Core Drilling Mention the core drill and why it is used to improve the concentricity of a cast hole.
- J. Reaming Demonstrate how a reamer is used for good control of both size and finish. Explain the relationship between the size of the reamer and the predrilled size.
- Mention that reaming is done to make a hole round, straight, smooth, and accurate.
- Emphasize that the hole must be drilled undersize before reaming. For example: Drill 1/64" undersize for holes over 3/8" in diameter.
- State that reamers and drills are held in the same way when used. Also, that reaming requires a slower speed than drilling.
- K. Lapping and Honing Demonstrate that under certain conditions abrasive cutting tools (either laps or hones) are used to size holes in hardened workpieces.

Job Sheets For Shop Projects

Unit No. Operator's Job Title: Drill Press Operator

Project I Project Name: Drill Stand

Job No. 1 Job Name: Drill Stand D.O.T. No. 606.380

Drawing Nos. 42

Time: 9 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Setting up.
2. Clamping
3. Drilling blind holes
4. Center drilling

Equipment:

Standard type drilling machine	Drill chucks
Fractional drill gage	Straight edge
Set of fractional drills $\frac{1}{32}$ " - $\frac{1}{2}$ " in increments of $\frac{1}{64}$ "	6" rule
	Clamping bolts
	Drill Vise
	Nos. 2 & 3 center drills

Materials:

One or more cast aluminum pcs. $1\frac{1}{2}$ " x 3" x 6" from milling and layout operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition

The Use and Care of Twist Drills

PROCEDURE

1. Select a cast aluminum block from stock and remove all burrs.
2. Set up a center drill in a quick-release drill chuck on a standard drill press.
3. Select drill speed and set spindle depth stop.
4. Clamp a guide bar to the table.
5. Center drill all hole locations in the line of smallest holes.
6. Remove the guide bar and reset to aline the middle line of holes.
7. Center drill the middle line of holes.
8. Remove the guide bar and reset and aline for the line of biggest holes.

TECHNIQUES AND RELATED INFO.

1. Check overall dimensions and layout before drilling.
2. Demonstrate the drill change-over procedure. Use a No. 1 center drill.
3. Check the recommended drill speed on a drill speed chart.
4. The guide bar will assist in keeping the holes in a straight line. Calculate the distance the bar should be set from the centerline of the drill spindle.
5. Use cutting lubricant.
6. Clean the guide bar and machine table with a brush. Calculate the distance the bar is to be set from the centerline of the spindle.
7. Use a No. 3 center drill.
8. Use a No. 3 center drill.

PROCEDURE

TECHNIQUES AND RELATED INFO.

9. Center drill the line of the biggest holes.
 10. Remove the guide bar and the center drill and clean the machine.
 11. Set the workpiece up in a drill vise.
 12. Set up a $\frac{1}{32}$ " drill and set the depth stop.
 13. Set the spindle r.p.m. and drill the $\frac{1}{32}$ " hole to the depth indicated on the drawing.
 14. Drill all the holes $\frac{1}{32}$ " through $\frac{1}{2}$ ", using the same procedure as above.
 15. Clean all tools and the machine on completion of the job.
10. Use a brush and a wiping cloth.
 11. Tap the workpiece down to seat it on the parallels, using a soft hammer.
 12. Check the drill size with a drill gage before chucking the drill. Discuss drill nomenclature.
 13. Refer to a drill chart for spindle speed.
 15. Use a wiping cloth and brush. Do not leave an excess of oil on the parallels or the drills. Return all tools to proper storage.

Unit No. Operator's Job Title: Drill Press Operator

Project 11 Project Name: Parallel Clamp

Job No. 1A Job Name: Loose Jaw (inches) D.O.T. No. 606.380

Drawing Nos. 57A, Ref. No. 3

Time: 4 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Setting up
2. Blind hole drilling
3. Tapping
4. Counterboring
5. Through hole drilling

Equipment:

Gang drill press Tapping head
 $\frac{1}{4}$ ", $\frac{11}{32}$ ", and No. 29 8-32 Go-No-Go plug
drills gage
 $\frac{7}{16}$ " counterbore Drill jig
8-32 UNC tap

Materials:

2 or more loose jaws SAE 1020
steel $\frac{1}{2}$ " x $\frac{1}{2}$ " x $3\frac{3}{8}$ " from milling
operations
Cutting oil

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select stock from milling operations and remove all burrs.
2. Clamp a workpiece in the drill jig.
3. Set up the cutting tools as follows:
Spindle No. 1: $\frac{1}{4}$ " drill
Spindle No. 2: $\frac{11}{32}$ " drill
Spindle No. 3: No. 29 drill
Spindle No. 4: $\frac{7}{16}$ " counterbore
Spindle No. 5: 8-32 UNC tap
Spindle No. 6: 90° countersink
4. Set the spindle speed for each of the spindles.
5. Drill the $\frac{1}{4}$ ", $\frac{11}{32}$ ", and No. 29 holes.
6. Tap the 8-32-UNC hole.

TECHNIQUES AND RELATED INFO.

1. Use a double-cut file. Check all dimensions before starting.
2. Drill jig will have to be constructed.
3. Clamp all tools securely. Use drill chucks for all drills, counterbores, and countersinks. Use a tapping head for the tap. Discuss turret head drill press as an alternate machine.
4. Look up the recommended r.p.m. for each of the operations.
5. Set each of the spindle depth stops. Check the depths with a depth micrometer and correct the stops if necessary.
6. Tapping head setup is in accordance with type of head being used. Remove slip bushing from jig before tapping. Use cutting oil.

PROCEDURE

TECHNIQUES AND RELATED INFO.

7. Counterbore $\frac{7}{16}$ " x $\frac{3}{32}$ " deep in the $\frac{11}{32}$ " hole.
 8. Remove the workpiece from the drill jig and take off all burrs by countersinking.
 9. Inspect the workpiece for hole sizes and depths.
 10. Continue to machine remaining workpieces.
 11. On completion of all pieces, clean the machine and remove all tools.
 12. Submit all work for inspection and grade.
7. Review counterbore types and sizes.
 8. Use a 90° countersink.
 9. Use a GO-No-Go thread plug gage.
 10. Make periodic inspections of workpieces.
 11. Clean tools with a rag. Return tools to proper storage.

Unit No. Operator's Job Title: Drill Press Operator

Project II Project Name: Parallel Clamp

Job No. 1B Job Name: Loose Jaw (millimeters) D.O.T. No. 606.380

Drawing Nos. 57B, Ref. No. 3 Time: 4 hrs.

Performance Objectives:
Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

- Operations:**
1. Setting up
 2. Blind hole drilling
 3. Tapping
 4. Counterboring
 5. Through hole drilling

- Equipment:**
- Gang drill press
 - 6.35 mm., 8.73 mm., and No. 29 drills
 - 11.11 mm. counterbore
 - 8-32 UNC tap
 - Tapping head
 - 8-32 Go-No-Go plug gage
 - Drill jig

- Materials:**
- 2 or more loose jaws SAE 1020
 - 12.8 mm. x 13 mm. x 85.7 mm. from milling operations
 - Cutting oil

Selected references:
McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

<u>PROCEDURE</u>	<u>TECHNIQUES AND RELATED INFO.</u>
1. Select stock from milling operations and remove all burrs.	1. Use a double-cut file. Check all dimensions before starting.
2. Clamp a workpiece in the drill jig.	2. Drill jig will have to be constructed.
3. Set up the cutting tools as follows: Spindle No. 1: 6.35 mm. drill Spindle No. 2: 8.73 mm. drill Spindle No. 3: No. 29 drill Spindle No. 4: 11.11 mm. counterbore Spindle No. 5: 8-32 UNC tap Spindle No. 6: 90° countersink	3. Clamp all tools securely. Use drill chucks for all drills, counterbores, and countersinks. Use a tapping head for the tap. Discuss turret head drill press as an alternate machine.
4. Set the spindle speed for each of the spindles.	4. Look up the recommended r.p.m. for each of the operations.
5. Drill the 6.35 mm., 8.73 mm., and No. 29 holes.	5. Set each of the spindle depth stops. Check the depths with a depth micrometer and correct the stops if necessary.
6. Tap the 8-32 UNC hole.	6. Tapping head setup is in accordance with type of head being used. Remove slip bushing from jig before tapping. Use cutting oil.



PROCEDURE

7. Counterbore 11.11 mm. x 2.38 mm. deep in the 8.73 mm. hole.
8. Remove the workpiece from the drill jig and take off all burrs by countersinking.
9. Inspect the workpiece for hole sizes and depths.
10. Continue to machine remaining workpieces.
11. On completion of all pieces, clean the machine and remove all tools.
12. Submit all work for inspection and grade.

TECHNIQUES AND RELATED INFO.

7. Review counterbore types and sizes.
8. Use a 90° countersink.
9. Use a Go-No-Go thread plug gage.
10. Make periodic inspections of workpieces.
11. Clean tools with a rag. Return tools to proper storage.

Unit No. Operator's Job Title: Drill Press Operator

Project 11 Project Name: Parallel Clamp

Job No. 2 Job Name: Threaded Jaw (inches) D.O.T. No. 606.380

Drawing Nos. 58A Ref. No. 3 Time: 5 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the Procedure column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Tapping
2. Countersinking
3. Through hole drilling

Equipment:

Gang drill press Tapping head
Drill jig 90° countersink
Drill chuck Go-No-Go thread
Letter F drill plug gage
 $\frac{5}{16}$ "-18 UNC tap

Materials:

2 or more threaded jaws SAE 1020,
 $\frac{1}{2}$ " x $\frac{1}{2}$ " x $3\frac{3}{8}$ " from milling operations

Selected references:

McCarthy & Smith, Machine Tool Technology; 3d edition
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

1. Select stock from milling operations and remove all burrs.
2. Place workpiece in drill jig and clamp it.
3. Set up the cutting tools as follows:
Spindle No. 1: Letter F drill
Spindle No. 2: $\frac{5}{16}$ "-18 UNC tap
Spindle No. 3: 90° countersink
4. Adjust the speeds and depth stops.
5. Drill the 2 holes (letter F drill) for the $\frac{5}{16}$ "-18 UNC tap.
6. Tap the $\frac{1}{6}$ holes.
7. Remove the work from the drill jig and take off all burrs.

1. Use a double-cut file. Check all sizes before proceeding.
2. Drill jig will have to be constructed.
3. Use a 2-fluted gun tap.
4. Calculate the r.p.m. in each case using the formula
$$RPM = \frac{4 \times CS}{D}$$
or use a drill speed chart. Set depth stop so the drill does not penetrate the machining table.
5. Use cutting oil.
6. Use cutting oil.
7. Use a 90° countersink.

PROCEDURES

TECHNIQUES AND RELATED INFO.

8. Inspect workpiece.
9. Remove all tools. Clean the machine and tools.
10. Submit all work for inspection and grade.

8. Remove all burrs and check the work with a $\frac{5}{16}$ " - 18 UNC Go-No-Go thread plug gage.
9. Use a wiping cloth. Return all tools to their proper locations.

Unit No. Operator's Job Title: Drill Press Operator

Project III Project Name: Parallels

Job No. 1A Job Name: Parallels (inches) D.O.T. No. 606.380

Drawing Nos. 50A

Time: 6 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Setting up fixture
2. Setting up spindle
3. Through hole drilling
4. Multiple spindle drilling

Equipment:

10-spindle drilling machine
Suitable drilling fixture
10 suitable $\frac{5}{16}$ " drills

Materials:

2 or more parallels from milling operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition

PROCEDURE

TECHNIQUE AND RELATED INFO.

- | | |
|--|--|
| <ol style="list-style-type: none">1. Select workpieces from milling operations and remove all burrs.2. Set up the drilling fixture.3. Set up the 10 tapered-shank drills of $\frac{5}{16}$" dia.4. Clamp the work in the drill fixture.5. Align the 10 drills to the drill bushings and clamp the spindles in place. If space is restricted, do 5 holes at a time in two settings.6. Set the spindle speed, depth stops, and all other necessary controls.7. Set all coolant nozzles. | <ol style="list-style-type: none">1. Inspect workpieces for sizes before proceeding.2. Discuss the design and purposes of work holding fixtures.3. Explain the Morse tapered system as applied to machine tools and drill diameters. Be sure all mating surfaces are clean and free of nicks and dirt.5. Fixtures are usually provided with hardened guide bushings. Discuss the use of laps to fit hardened bushings.6. Be sure all drills are of the same approximate length. Demonstrate the freehand method of sharpening a twist drill. Use a drill point gage.7. Coolant flow should be directed on the drill bushings. |
|--|--|

PROCEDURE

8. Drill the holes.
9. Remove and inspect the workpiece.
10. If first piece is correct, continue to drill the assigned number of pieces. If not, make necessary adjustments.
11. Remove all tools. Clean the tools and machine on completion of the work.
12. Submit all workpieces for inspection and grade.

TECHNIQUES AND RELATED INFO.

8. Observe the drill entering the drill bushings for drill deflection.
10. Clean the fixture of chips before inserting each new piece.
11. Use a shop cloth. Return all tools to their proper storage places.

Unit No. Operator's Job Title: Drill Press Operator
Project III Project Name: Parallels
Job No. 1B Job Name: Parallels (millimeters) D.O.T. No. 606.380

Drawing Nos. 50B

Time: 6 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Setting up fixture
2. Setting up spindle
3. Through hole drilling
4. Multiple spindle drilling

Equipment:

10-spindle drilling machine
Suitable drilling fixture
10 suitable 8 mm. drills

Materials:

2 or more parallels from milling operations SAE 1020
13 mm. x 19 mm. x 150 mm.

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select workpieces from milling operations and remove all burrs.
2. Set up the drilling fixture.
3. Set up the 10 tapered-shank drills of 8 mm. dia.
4. Clamp the work in the drill fixture.
5. Aline the 10 drills to the drill bushings and clamp the spindles in place. If space is restricted, do 5 holes at a time in two settings.
6. Set the spindle speed, depth stops, and all other necessary controls.
7. Set all coolant nozzles.

TECHNIQUES AND RELATED INFO.

1. Inspect workpieces for sizes before proceeding.
2. Discuss the design and purposes of work holding fixtures.
3. Explain the Morse tapered system as applied to machine tools and drill diameters. Be sure all mating surfaces are clean and free of nicks and dirt.
5. Fixtures are usually provided with hardened guide bushings. Discuss the use of laps to fit hardened bushings.
6. Be sure all drills are of the same approximate length. Demonstrate the freehand method of sharpening a twist drill. Use a drill point gage.
7. Coolant flow should be directed on the drill bushings.

PROCEDURE

TECHNIQUES AND RELATED INFO.

- | | |
|--|--|
| <p>8. Drill the holes.</p> <p>9. Remove and inspect the workpiece.</p> <p>10. If first piece is correct, continue to drill the assigned number of pieces. If not, make necessary adjustments.</p> <p>11. Remove all tools. Clean the tools and machine on completion of the work.</p> <p>12. Submit all workpieces for inspection and grade.</p> | <p>8. Observe the drill entering the drill bushings for drill deflection.</p> <p>10. Clean the fixture of chips before inserting each new piece.</p> <p>11. Use a shop cloth. Return all tools to their proper storage places.</p> |
|--|--|

Unit No. Operator's Job Title: Drill Press Operator

Project IV Project Name: Bench Vice

Job No. 1 Job Name: Screw D.O.T. No. 606.380

Drawing Nos. 16


Time: 1 1/2 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Equipment:

Standard drill press
V-block
Speed chuck
90° countersink
17/64" drill



Operations:

1. Through hole drilling
2. Center drilling

Materials:

Bench vice screw from lathe operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select workpiece from lathe and layout operations.
2. Clamp workpiece in a suitable V-block.
3. Clamp a center drill in the speed chuck.
4. Set the spindle speed and center drill.
5. Remove the center drill and insert a 17/64" dia. drill.
6. Drill the 17/64" hole through the piece.

TECHNIQUES AND RELATED INFO.

1. Check all dimensions before proceeding.
2. Review uses and purposes of V-blocks as well as the various types. Do not clamp on the thread.
3. Point out that center drills come in various designs and sizes. Also, that there are charts recommending the sizes to be used. Illustrate the various kinds of drill chucks available and their purposes.
4. Use a moderate feed pressure.
5. Point out that the spindle does not have to be stopped to change the cutting tools.
6. Use cutting oil. Be careful that the V-block does not tilt which could result in a slanted hole. Use a jack if necessary.

PROCEDURE

TECHNIQUES AND RELATED INFO.

7. Remove the $\frac{17}{64}$ " drill and insert a 60° countersink.
8. Break all sharp edges around the hole.
9. Clean all tools and machine.
10. Submit for inspection and grade.

8. Point out that countersinks come in various angles and diameters.
9. Return all tools to proper locations.

PROCEDURE

TECHNIQUES AND RELATED INFO.

- | | |
|--|--|
| 11. Ream the two outer holes. | 11. Use cutting oil. |
| 12. Replace the reamer with a drill chuck and a 90° countersink. | |
| 13. Break all sharp edges on both ends of all holes. | |
| 14. Insert a drill chuck center in the drill chuck and aline it with the $\frac{27}{64}$ " hole. | 14. Center will be used to keep tap square with hole. |
| 15. Tap the hole. | 15. Use a flat tap wrench to drive the tap by hand. (Demonstrate the procedure.) |
| 16. Send the work to the band saw to be cut into the two jaws and then to milling for finishing. | |
| 17. On return from milling, ream the remaining middle $\frac{1}{2}$ " hole in the movable jaw. | |
| 18. Clean all tools and the machine. | 18. Return all tools to the proper places. |
| 19. Submit for inspection and grade. | |

Unit No. Operator's Job Title: Drill Press Operator

Project V Project Name: Arbor Press

Job No. 1 Job Name: Base

D.O.T. No. 606.380

Drawing Nos. 33

Time: 3 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Small hole drilling
2. Clamping
3. Reaming
4. Blind hole drilling
5. Tapping

Equipment:

Standard drill press	T-bolts and nuts
$\frac{1}{8}$ " , $\frac{3}{16}$ " and $\frac{15}{64}$ " drills	Gooseneck clamps
$\frac{1}{4}$ " rose reamer	Parallels
Letter F drill	Angle plate
$\frac{3}{8}$ " - 16 UNC tap	Vise
	Tapping head

Materials:

Arbor press base 1" x 3" x $3\frac{1}{4}$ "
from milling and layout operations

Selected references:

McCarthy & Smith. *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

1. Select stock from milling and layout operations before the slots are milled.
2. Clamp the workpiece in a drill vise with step jaws.
3. Insert a $\frac{1}{8}$ " drill in the drill chuck.
4. Drill the two $\frac{1}{8}$ " holes.
5. Remove the $\frac{1}{8}$ " drill and replace it with a $\frac{3}{16}$ " drill.
6. Drill the two $\frac{3}{16}$ " holes.
7. Remove the $\frac{3}{16}$ " drill, insert a $\frac{15}{64}$ " drill, and drill the hole for the $\frac{1}{4}$ " reamer.

1. Inspect workpiece for correctness of sizes before proceeding with the drilling.
2. Tap the work down with a soft hammer to seat it.
3. Use a quick release chuck. Check the drill for runout.
4. Do not allow the chips to become clogged in the flutes of the drill. Raise spindle frequently. Use cutting oil.
5. Do not allow the chips to become clogged in the flutes of the drill. Raise spindle frequently. Use cutting oil.
6. Clear the chips from the hole frequently.
7. Drill to $\frac{1}{8}$ " depth and check hole for oversize condition with the reamer before drilling through.

PROCEDURE

TECHNIQUES AND RELATED INFO.

8. Remove the $\frac{15}{64}$ " drill, replace it with a $\frac{1}{4}$ " rose reamer, and ream the hole.
 9. Remove the workpiece from the vise and clamp it to an angle plate.
 10. Locate the point for drilling the tapped hole and clamp the angle plate to the machine table.
 11. Set the depth stop to $\frac{3}{4}$ " and drill the $\frac{5}{16}$ " drill hole for the $\frac{3}{8}$ " - 16 UNC tapped hole.
 12. Open the $\frac{5}{16}$ " hole to $\frac{3}{8}$ " dia. to a depth of $\frac{1}{8}$ ".
 13. Tap the $\frac{3}{8}$ " thread.
 14. Clean machine and all tools.
 15. Return all tools to their proper storage places.
 16. Submit work for inspection and grade.
8. Check the reamer to see that it is in good condition before using it. Use cutting oil.
 9. Check the angle plate for squareness. Use parallel clamps.
 10. Use T-bolts, straps, clamps, and step blocks.
 11. Use cutting oil. Hole depth is at full dia.
 12. This will provide relief for the tap.
 13. Use an extension tap. Follow local shop setup procedure.
 14. Use a brush and a shop cloth.

Unit No. Operator's Job Title: Drill Press Operator
Project VI Project Name: Tap Wrench
Job No. 1 Job Name: Tap Wrench Body D.O.T. No. 606.380

Drawing Nos. 21

Time: 1½ hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Equipment:

Standard drill press 90° countersink
Center drill Rapid index head
Drill chuck $\frac{3}{4}$ " collet
 $\frac{1}{8}$ " drill Clamps

Operations:

1. Setting up
2. Drilling
3. Alining spindle with hole layout

Materials:

Wrench body from lathe and layout operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select material from lathe operations and layout. Remove all burrs.
2. Clamp work in a rapid index head with a $\frac{3}{4}$ " collet.
3. Insert a drill chuck in the spindle.
4. Clamp a center drill in the drill chuck and center drill for the $\frac{1}{4}$ " hole.
5. Drill the $\frac{1}{4}$ " hole through the $\frac{3}{4}$ " dia.
6. Remove the $\frac{1}{8}$ " drill and replace it with a 90° countersink.
7. Countersink both ends of the $\frac{1}{4}$ " hole.
8. Remove all tools. Clean the tools and the machine.
9. Submit job for inspection and grade.
10. Send to lathe for drilling and tapping of the 10-32 UNC-2A hole.

TECHNIQUES AND RELATED INFO.

1. Check all sizes before proceeding with drilling operations.
2. Aline spindle with hole layout and index head with table. Use a surface gage and suitable clamp.
3. Clean the tapered shank and the spindle hole with a shop cloth.
4. Check drill for runout. Use cutting oil.
5. Ease the feed pressure when the drill breaks through the work.
8. Return all tools to proper storage. Use a rag to remove all chips and oil.

Unit No. Operator's Job Title: Drill Press Operator

Project VII Project Name: 1-2-3 Block

Job No. 1 Job Name: 1-2-3 Block D.O.T. No. 606.380

Drawing Nos. 45.1

Time: 5 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Setting up
2. Countersinking
3. Reaming
4. Drilling

Equipment:

Standard drill press $\frac{1}{2}$ " reamer
Box drill jig Fractional drill gage
 $\frac{3}{16}$ " drill Countersink

Materials:

2 or more pcs. SAE 1020
1.020" x 2.020" x 3.020"
from milling operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills.

PROCEDURE

TECHNIQUES AND RELATED INFO.

- | | |
|--|---|
| <ol style="list-style-type: none">1. Select material from milling operations. Remove all burrs.2. Chuck a $\frac{3}{16}$" drill.3. Clamp the workpiece in a drill jig.4. Select and set spindle speed and depth stop.5. Drill the 13 holes. Drill first hole to $\frac{1}{8}$" depth and check hole for oversize condition before drilling through.6. Replace the drill with a $\frac{1}{2}$" rose reamer.7. Change the spindle speed and the depth stop.8. Ream all 13 holes. | <ol style="list-style-type: none">1. Check sizes before proceeding with drilling operations.2. Check the drill size with a drill gage.3. For hole location, use a plate template or a box drill jig.4. Look up speed on a chart.5. Use cutting oil and power feed.6. If a box jig is used, change the slip bushings to accommodate the $\frac{1}{2}$" reamer, otherwise follow local shop practice. Another method that could be used is to layout the holes and drill them while holding the work in a drill vise.8. Use cutting oil and hand feed. |
|--|---|

PROCEDURE

TECHNIQUES AND RELATED INFO.

9. Replace the reamer with a $\frac{3}{4}$ " 90° countersink and change the spindle speed.
10. Remove the work from the box drill jig. Clean the work and the machine table.
11. Remove all burrs.
12. Set the work up in a drill vise.
13. Set the depth stop to countersink to $\frac{1}{32}$ " depth.
14. Countersink all 13 holes, both ends.
15. Clean the machine and all tools.
16. Submit all work for inspection and grade.

9. Use a slow speed to avoid chatter.
10. Use a brush.
11. Use a double-cut file.
13. CAUTION: Each dimension will require a change in the depth stop.
15. Return all tools to the proper locations.

Unit No. Operator's Job Title: Drill Press Operator

Project VIII Project Name: Micrometer Boring Head

Job No. 1 Job Name: Dovetail Blocks

D.O.T. No. 606.380

Drawing Nos. 22.2

Time: 2½ hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the Procedure column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Center drilling
2. Through hole drilling
3. Countersinking
4. Subland drilling

Equipment:

Standard drill press
No. 2 center drill
 $\frac{11}{64}$ " drill
 $\frac{21}{64}$ " x .437" subland drill
Drill vise and special clamping jaw
Flush gage
90° countersink
Drill gage

Materials:

2 dovetail blocks from milling operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select stock from milling operations and remove all burrs.
2. Clamp the laid-out dovetail block in a drill vise using a special 8° soft, parallel clamping block.
3. Clamp a center drill in a drill chuck and center drill all 6 holes.
4. Set up a $\frac{11}{64}$ " drill and drill 4 holes.
5. Remove the $\frac{11}{64}$ " drill and replace it with a $\frac{21}{64}$ " x .437" subland drill.
6. Set the r.p.m. and the depth stop.
7. Drill and counterbore the $\frac{21}{64}$ " x .437" holes to .345" depth.
8. Remove the workpiece from the vise and turn it and the 8° clamping block over.

TECHNIQUES AND RELATED INFO.

1. Check all sizes before proceeding.
2. Either an 8° clamping block should be constructed or an alternate machining method. The alternate method could be to cut the block in two and clamp the pieces in a vise.
3. Set the spindle depth stop to obtain a $\frac{7}{32}$ " dia. countersink. Use cutting oil.
4. Check the drill size using a fractional drill gage. Do not allow drill to become clogged with chips.
5. Describe the advantages and the uses of subland and step drills.
7. Use cutting oil. Check the counterbore depth using a flush gage.
8. Clean and remove burrs from workpiece, clamping block, and vise.

PROCEDURE

TECHNIQUES AND RELATED INFO.

9. Remove the subland drill and replace it with a 90° countersink.
10. Adjust the r.p.m. of the machine spindle.
11. Countersink the four $\frac{11}{64}$ " holes to $\frac{7}{32}$ " dia.
12. Countersink the two $\frac{21}{64}$ " holes to break the sharp edges.
13. Clean all tools and the machine.
14. Submit workpiece for inspection and grade.

10. Calculate the r.p.m. using the formula

$$\text{R.P.M.} = \frac{4 \times \text{CS}}{D}$$

or a chart.

11. Set the spindle depth stop.
12. $\frac{11}{32}$ " dia. should be suitable.
13. Return all tools to proper storage places.
14. Send to Power Saws and Milling Machine for completion of operations.

Unit No. Operator's Job Title: Drill Press Operator

Project IX Project Name: Precision Step Block

Job No. 1 Job Name: Precision Step Block D.O.T. No. 606.380

Drawing Nos. 44

Time: 2½ hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Clamping
2. Center drilling
3. Drilling
4. Counterboring
5. Countersinking
6. Spindle alignment
7. Deep hole drilling

Equipment:

Standard drill press $\frac{5}{16}$ " drill
Drill vise $\frac{7}{16}$ " counterbore
T-bolts and nuts $\frac{3}{4}$ " x 90° countersink
Dial indicator
Wiggler
Center drill

Materials:

Tool steel step block from milling and layout operations

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition.
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

1. Check the machine table for squareness to the drill press spindle.
 2. Select stock from milling and layout operations and check dimensions.
 3. Clamp the work in a vise with step jaws.
 4. Set up a centerfinder and locate the centerlines for the hole.
 5. Clamp the vise securely when location is found.
 6. Centerdrill for the $\frac{5}{16}$ " hole.
 7. Remove the center drill and drill the $\frac{5}{16}$ " hole through the work.
 8. Remove the $\frac{5}{16}$ " drill and replace it with a $\frac{7}{16}$ " counterbore.
1. Use a dial indicator mounted in a drill chuck on a bent bar, and sweep the table by revolving the spindle. Indicator should read the same at four points opposite to each other. Adjust table if necessary.
 2. Do not proceed if dimensions are not correct.
 3. Use a soft hammer to seat the work.
 4. Demonstrate the use of the centerfinder.
 5. Check with centerfinder again, after clamping the vise, to be sure the latter did not shift.
 7. Use cutting oil and raise the spindle frequently to clear out the chips.
 8. Review types and sizes of counterbores.

PROCEDURE

TECHNIQUES AND RELATED INFO.

9. Set the r.p.m. and counterbore to $\frac{5}{16}$ " depth.
10. Remove the counterbore and set up a 90° countersink.
11. Countersink to $\frac{1}{16}$ " depth.
12. Remove the burrs and turn the workpiece over in the vise.
13. Loosen the vise and chuck a $\frac{7}{16}$ " counterbore.
14. Counterbore the $\frac{5}{16}$ " hole to a depth of $\frac{5}{16}$ ".
15. Remove the counterbore and chuck a 90° countersink.
16. Countersink to $\frac{1}{16}$ " depth.
17. Remove burrs.
18. Submit work for inspection and grade.

9. Use cutting oil. Set the depth stop. Use a moderate hand feed rate.
11. Use a slow spindle speed to avoid chatter. Use cutting oil.
12. Clean the vise and put side D down on the parallels.
13. Aline the pilot of the counterbore in the $\frac{5}{16}$ " hole and carefully clamp the vise.
14. Use cutting oil and a moderate feed pressure.
17. Clean all tools and machine. Return all tools to their proper locations.

Unit No. Operator's Job Title: Drill Press Operator
Project X Project Name: Motor Plate
Job No. 1 Job Name: A, B, and C Holes D.O.T. No. 606.380

Drawing Nos. 72

Time: 2 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Locating spindle in relation to layout
2. Center drilling
3. Drilling
4. Counterboring
5. Facing
6. Back facing

Equipment:

Single-spindle upright-drill or small radial drill
Drill press vise with step jaws
 $\frac{13}{32}$ " and $\frac{19}{32}$ " counterbores
Depth gage
 $\frac{7}{8}$ " facer with $\frac{13}{32}$ " pilot
Mill file
 $\frac{1}{2}$ " back facer with $\frac{19}{32}$ " pilot
Center drill
 $\frac{19}{32}$ " drill

Materials:

$1\frac{1}{4}$ " X $4\frac{1}{4}$ " x $6\frac{1}{4}$ "
cast iron plate
from milling and
layout operations

Selected references:

McCarthy & Smith. *Machine Tool Technology*;
3d edition
The Use and Care of Twist Drills

PROCEDURE

1. Select stock and deburr.
2. Insert part, clamp, and seat in step jaws.
3. Mount center drill in chuck, and move vise on table until center punch mark is directly below the drill for one of the "A" holes.
4. Clamp vise to table.
5. Hand feed center drill to full 60° depth.
6. Drill the $\frac{13}{32}$ " hole through.
7. Counterbore .594"x.531" deep.
8. Loosen vise and repeat above procedure for the other 3 "A" holes.
9. Move to the "B" hole and drill $\frac{13}{32}$ " through.

TECHNIQUES AND RELATED INFO.

1. Check overall dimensions and layout before starting.
3. Discuss alternate methods. For example: using wiggler or spotting with small diameter drill.
4. If radial drill is being used, move head over punch mark.
6. Use power feed .005"-.007" and proper r.p.m.
7. Use hand feed and proper r.p.m. Demonstrate use of depth gage.
9. Use power feed .005"-.007" and proper r.p.m.

PROCEDURE

TECHNIQUES AND RELATED INFO.

10. Face to depth with $\frac{7}{8}$ " facer.
11. Move to location of "C" hole.
12. Drill $\frac{19}{32}$ " hole through.
13. Insert back facer with $\frac{19}{32}$ " shank in chuck and drop through hole. Attach facer tool on shank and raise spindle up to face underside of part.

10. Use hand feed.
12. Use power feed .005"-.007" and proper r.p.m.
13. Hand feed upward to clean up surface. Discuss the importance of proper tool assembly so that the opposing cutting force does not pull out the back facer.

Unit No. Operator's Job Title: Drill Press Operator

Project X Project Name: Motor Plate

Job No. 2 Job Name: D Holes D.O.T. No. 606.380

Drawing Nos. 72

Time: $1\frac{1}{2}$ hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Locating spindle in relation to layout
2. Center drilling
3. Drilling
4. Machine reaming
5. Hand reaming

Equipment:

Single-spindle upright $\frac{15}{32}$ " drill
drill or small radial $\frac{1}{2}$ " drill
drill $\frac{1}{2}$ " Go-No-Go plug
Drill press vise with gage.
step jaws $\frac{1}{2}$ " spiral flute
Center drill expansion hand reamer

Materials:

$1\frac{1}{4}$ " x $4\frac{1}{4}$ " x $6\frac{1}{4}$ " cast iron plate
 $\frac{1}{2}$ " machine reamer (undersize)
Flat tap wrench

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

1. Locate spindle on layout for one "D" hole and center drill it.
2. Drill through with $\frac{15}{32}$ " drill (2 "D" holes).
3. Ream $\frac{1}{2}$ "-.010 hole. Check with a micrometer. Locate the chamfer of the reamer in the drilled holes. Repeat for other "D" hole.
4. Check the holes with a .500" Go-No-Go gage.
5. Use expansion hand reamer until the Go-Gage enters and the No-Go does not.

1. Use same procedure as for holes A, B, and C in Job 1.
2. Use .007" feed and proper r.p.m.
3. Discuss the differences between rose and chucking reamers. Engage feed lever then engage r.p.m. lever. Feed .015". The r.p.m. for reaming is one-half of that for drilling.
4. At this stage neither end should enter.
5. Demonstrate how to back the reamer off so it just passes through the hole; then expand it $\frac{1}{8}$ turn for each pass.

Unit No. Operator's Job Title: Drill Press Operator

Project X Project Name: Motor Plate

Job No. 3 Job Name: E Holes D.O.T. No. 606.380

Drawing Nos. 72

Time: 2 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Locating spindle in relation to layout
2. Center drilling
3. Drilling
4. Countersinking
5. Power tapping

Equipment:

Single-spindle upright drill
or small radial drill $\frac{3}{8}$ "-16 plug tap
Drill Press vise $\frac{3}{8}$ "-16 plug thread
Center drill gage (Go-No-Go)
 $\frac{5}{16}$ " drill 90° countersink

Materials:

$1\frac{1}{4}$ " x $4\frac{1}{4}$ " x $6\frac{1}{4}$ " cast iron plate

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

1. Locate the spindle on the layout for one of the "E" holes and center drill it.
2. Drill through with $\frac{5}{16}$ " drill. Repeat for the other 3 "E" holes.
3. Countersink 90° to width $\frac{1\frac{3}{32}}$ " at top of hole.
4. Tap through $\frac{3}{8}$ "-16. Use soluble oil.
5. Check threads with $\frac{3}{8}$ "-16 thread plug gage. The "Go" end should enter freely, the "No-Go" end only 1 to $1\frac{1}{2}$ threads deep.

1. Use same procedure as for holes A, B, C, and D.
2. Use .007" feed. Figure r.p.m.
3. Discuss purpose of countersinking.
4. Use proper r.p.m. Put spindle in forward, and allow tap to pull itself in and through the hole. Before tap reaches end of threads, reverse it and apply light lifting pressure.

Unit No. Operator's Job Title: Drill Press Operator
 Project X Project Name: Motor Plate
 Job No. 4 Job Name: F and G Holes D.O.T. No. 606.380

Drawing Nos.: 72 Time: 3 hrs.

Performance Objectives:
 Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the Procedure column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:
 1. Locate spindle in relation to layout
 2. Center drilling
 3. Drilling
 4. Powertapping

Equipment:
 Single-spindle upright drill or small radial drill
 $\frac{37}{64}$ " drill
 Letter R drill
 $\frac{3}{8}$ "-18 National pipe tap
 $\frac{1}{8}$ "-27 pipe tap
 $\frac{7}{16}$ " counterbore
 $\frac{1}{16}$ "-27 NP thread plug gage
 $\frac{3}{8}$ "-18 hole gage
 $\frac{1}{8}$ "-27 hole gage
 $\frac{3}{8}$ "-18 NP thread plug gage

Materials:
 $1\frac{1}{4}$ " x $4\frac{1}{4}$ " x $6\frac{1}{4}$ " cast iron plate

Selected references:
 McCarthy & Smith, *Machine Tool Technology*; 3d edition
The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

- | | |
|---|--|
| <ol style="list-style-type: none"> 1. Locate spindle in relation to layout for "F" holes and center drill. 2. Drill through with $\frac{37}{64}$" drill (2 holes). 3. Tap with $\frac{3}{8}$"-18 pipe tap (2 holes). 4. Clean out thread and check with thread gage. Repeat until desired depth is obtained. 5. Recheck with hole gage. 6. Turn part on end, locate the spindle on the layout for hole "G", and center drill. 7. Drill through with R drill. 8. Tap with $\frac{1}{8}$"-27 pipe tap. 9. Counterbore $\frac{7}{16}$" x .0625. | <ol style="list-style-type: none"> 1. Use same procedure as for holes A, B, and C. 2. Demonstrate that hole gage should not enter hole. 3. Discuss importance of thread depth. Tap should not enter over half the threads. 4. Gage should not go beyond ground flat on gage. 5. After tapping to proper depth, the hole gage should not enter hole more than 1 to $1\frac{1}{2}$ threads deep. 6. Use same procedure as for holes A, B, and C. 7. Demonstrate that the hole gage should not enter the hole. 8. Use same procedure as for hole F, steps 3 and 5. 9. Use depth gage. |
|---|--|

Unit No. Operator's Job Title: Drill Press Operator

Project X Project Name: Motor Plate

Job No. 5 Job Name: H Hole D.O.T. No. 606.380

Drawing Nos. 72

Time: 2 hrs.

Performance Objectives:

Using only the equipment and materials listed here, the student will be able to perform the drilling operations described in the *Procedure* column below as shown on the drawings, in accordance with the time and accuracy requirements specified. After completing this job, the student will be able to complete similar jobs with like specifications.

Operations:

1. Locating spindle in relation to layout
2. Drilling
3. Machine reaming
4. Hand reaming
5. Countersinking

Equipment:

Center drill No. 4 taper pin
 $\frac{7}{32}$ " drill Drill press vise

No. 4 straight or spiral-flute taper-pin reamer

Tap wrench

Hammer

Materials:

$1\frac{1}{4}$ " x $4\frac{1}{4}$ " x $6\frac{1}{4}$ " cast iron plate

Selected references:

McCarthy & Smith, *Machine Tool Technology*; 3d edition

The Use and Care of Twist Drills

PROCEDURE

TECHNIQUES AND RELATED INFO.

- | | |
|---|---|
| <ol style="list-style-type: none">1. Turn the part back to its original position in the vise and position the spindle on the layout for hole H. Center drill for the hole.2. Drill through with $\frac{7}{32}$" drill.3. Machine ream part way. Use hand feed.4. Clean out hole, try pin, ream until pin extends out top of hole about $\frac{1}{4}$".5. Hand ream until pin extends out about $\frac{1}{8}$".6. Countersink both sides of all holes to break edges $\frac{1}{32}$".7. After completion of piece, clean the machine.8. Submit all work for inspection and grade. | <ol style="list-style-type: none">1. Use the same procedure as for holes A, B, and C.3. Use r.p.m. of half the drill speed.5. Clean hole and pin. Oil pin to prevent pickup. Tap pin into position with hammer. Rounded portion of large dia. of pin should be flush or barely above surface.7. Clean tools with a rag. Return tools to proper storage places. |
|---|---|

Bibliography

Anderson, James & Tatro, Earl E. *Shop theory*; 6th ed. New York, N.Y. McGraw-Hill. 1974.

Beloit Tool Corp. *U.S.A. goes metric*; rev. ed. Swan Publishing Co., Box 248, Roscoe, Ill. 61080. Undated.)

Colvin, Fred H. *New American machinist's handbook*. New York, N.Y. McGraw-Hill. 1955.

Feirer, John L. *Machine tool metalworking: principles and practices*; 2d ed. New York, N.Y. McGraw-Hill. 1973.


McCarthy, Willard J. & Smith, Robert E. *Machine tool technology*; 3d ed. Bloomington, Ill. McKnight & McKnight. 1968. (Order from Taplinger Publishing Co., 200 Park Ave., S., New York, N.Y. 10003.)

Oberg, Erik & Jones, Franklin D. *Machinery's handbook*; 19th ed. New York, N.Y. Industrial Press. 1971.

Use and care of twist drills. Cleveland Twist Drill Co., 1242 E. 49th St., Cleveland, O. Undated. (Free in limited quantities.)

Walker, John R. *Machining fundamentals*. South Holland, Ill. Goodheart-Wilcox Co. 1973.

Drawings For Shop Projects




DRAWN BY: E.F.S.

SCALE: —

CLOSE QUARTERS HACKSAW
ASSEMBLY

DWG. NO. 13




WORK AS SOLID PIECE.
 AFTER ALL MACHINING,
 CUT IN HALF ON BANDSAW
 AND MILL SAW CUTS TO
 SIZE.

DRAWN BY: E.F.S.
 SCALE: —

BENCH VISE ASSEMBLY

DWG. NO. 15



DRAWN BY: E.F.S.
SCALE: _____

BENCH VISE DETAILS

DWG. NO. 16





PARTS LIST

NO.	NAME	MATL.	REQD.
1	GRADUATED DIAL	CRS	1
2	PLATE	CRS	1
3	SHANK	CRS	1
4	DOVETAIL BLOCKS	CRS	2
5	DOVETAIL SLIDE	CRS	1
6	DOWEL PIN $\frac{3}{16}$ DIA. x $\frac{1}{4}$	CRS	4
7	HEX. HD. CAP. SCR. $\frac{5}{16}$ -18 UNC	CRS	2
8	STOP PIN	CRS	1

NOTES:

1. PARTS 2 AND 4 ARE MILLING MACHINE PROJECTS.
2. PARTS 6 AND 7 ARE PURCHASED.
3. PARTS 2, 4 AND 5 ARE ASSEMBLED TO A 2" SQ. AND THEN MACHINED ROUND.




MICROMETER BORING HEAD ASSEMBLY

DRAWN BY: E.F. S.

SCALE: _____

DWG. NO. 22

$\frac{29}{64}$ DR. & $\frac{1}{2}$ -20UNF-2B } locate when assembling.
 $\frac{15}{64}$ DR. & $\frac{1}{4}$ REAM



(2) MATL. C R S
 FAO

TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 ± .005 DECIMAL
 ± $\frac{1}{64}$ FRACTIONAL
 ± 1° ANGULAR

DRAW BY: E.F.S.



SCALE: _____

MICROMETER BORING HEAD
 PLATE

DWG. NO. 22.1

2 1/64 DRILL, .437 C BORE, x.343 DR
2 HOLES

11/64 DRILL, 7/32 CSK.
(3/16 REAM AT ASSY)
4 HOLES




4
MATERIAL: CRS (SAE 1020) or PHOSPHOR
BRONZE (SAE 64)
FAO
2 REQD.


TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
± .005 DECIMAL
± 1/64 FRACTIONAL
± 1/2° ANGULAR

DRAWN BY: E.F.S.	MICROMETER BORING HEAD DOVE TAIL BLOCKS	DWG. NO. 22.2
		SCALE: _____





① DIAL
 MATL. CRS
 CASE HARDEN
 TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 ±.005 ON DECIMAL DIMENSIONS
 ± 1/64 ON FRACTIONAL DIMENSIONS
 ± 1° ON ANGULAR DIMENSIONS



③ SHANK
 MATL. CRS
 FAO


⑧ STOP PIN
 MATL. DR. ROD HARDENED
 FAO

DRAWN BY: E.F.S.


SCALE: —

MICROMETER BORING HEAD
 DIAL, SHANK, AND STOP PIN

DWG. NO. 23



TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 $\pm .005$ ON DECIMAL DIMENSIONS
 $\pm \frac{1}{64}$ ON FRACTIONAL DIMENSIONS
 $\pm 1^\circ$ ON ANGULAR DIMENSIONS




5 DOVETAIL SLIDE
 MATL. CRS
 FAO

DRAWN BY: E.F.S.

SCALE: _____

MICROMETER BORING HEAD
 DOVETAIL SLIDE

DWG. NO.24



4 NO. 8-32 UNC x 1/2
FILLISTER
HEAD SCREWS

1/8 DOWEL
PIN


3-16 UNC x 1-8
HEX. SOC. HD.
CAP SCREW

ARBOR PRESS
ASSEMBLY

DWG. NO. 27

DRAWN BY: E.F.S.

SCALE: _____



TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 ± .005 ON DECIMAL DIMENSIONS
 ± 1/64 ON FRACTIONAL DIMENSIONS
 ± 1° ON ANGULAR DIMENSIONS

12 MATL. C1020
 1 REQD.


NOTE:
 COUNTERSINK ALL HOLES
 TOP AND BOTTOM 1/2 DEEP
 BEFORE SLOTTING. 3/32

DRAWN BY: E.F. S.

SCALE: _____


ARBOR PRESS
 TABLE

DWG. NO. 29




⑨ SLEEVE
MATL.C1010
1 REQD.

PRESS FIT IN PT. 12
LOOSE FIT IN PT. 1



⑩ TABLE PIN
MATL.C1020
1 REQD.



⑪ COVER PLATE
MAT L.C1010
1 REQD.

TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
± .005 ON DECIMAL DIMENSIONS
± 1/64 ON FRACTIONAL DIMENSIONS
± 1° ON ANGULAR DIMENSIONS

DRAWN BY: E.F.S.

SCALE: _____

ARBOR PRESS
SLEEVE, TABLE PIN AND COVER PLATE


DWG. NO. 30

NO. 20 DR. x $\frac{3}{4}$ DEEP,
10-32 UNC-2B x $\frac{1}{2}$ DEEP,
2 HOLES

$\frac{3}{8}$ DIA.


$\frac{7}{8}$

7 HANDLE
MATL. C1020
1 REQD.




8 GEAR SHAFT SCREW
MATL. C1020
1 REQD.

NO. 10 DRILL THROUGH,
 $\frac{5}{16}$ DIA. CBORE x $\frac{3}{16}$ DEEP,
 $\frac{1}{32}$ CSK. BOTH SIDES



6 HANDLE END
MATL. CRS
2 REQD.



TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
 $\pm .005$ ON DECIMAL DIMENSIONS
 $\pm \frac{1}{64}$ ON FRACTIONAL DIMENSIONS
 $\pm 1^\circ$ ON ANGULAR DIMENSIONS

DRAWN BY: E.F.S.

SCALE: —


ARBOR PRESS
HANDLE AND END

DWG. NO. 31

NO. 28 DRILL, 8-32 UNC-2B x $\frac{1}{2}$
LOCATE FROM PART II

500 REAM 1.168 C'BORE x $\frac{47}{64}$
FROM BACK SIDE

GRIND SLOT TO
FIT RACK



TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
±.005 ON DECIMAL DIMENSIONS
± 1/64 ON FRACTIONAL DIMENSIONS
± 1° ON ANGULAR DIMENSIONS

(2) MAT L.C1020
1 REQD.

DRAWN BY: E.F.S.


SCALE: _____

ARBOR PRESS
COLUMN

DWG.NO.32


GRIND SLOT TO
FIT COLUMN

$\frac{1}{16}$ x 45° BEVELED EDGES
(TOP AND SIDES)



TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
±.005 ON DECIMAL DIMENSIONS
± $\frac{1}{64}$ ON FRACTIONAL DIMENSIONS
±1° ON ANGULAR DIMENSIONS

MATL. C1020
1 REQD.




ARBOR PRESS
BASE

DRAWN BY: E.F.S.

SCALE: —

DWG. NO. 33





TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 $\pm .005$ DECIMAL
 $\pm \frac{1}{64}$ FRACTIONAL
 $\pm \frac{1}{2}^\circ$ ANGULAR

NOTES:
 MATL. CAST ALUM.
 HOLES GO FROM $\frac{1}{32}$ TO $\frac{1}{2}$ BY $\frac{1}{64}$ ths
 FAO


DRAWN BY: E. F. S.		DRILL STAND	DWG. NO. 42
SCALE: _____			

MILLIMETER
INCH

NOTES:
MATL. SAE 1020
CASE HARDEN.
BREAK ALL SHARP CORNERS.
2 REQD.



12.3 $\frac{3}{64}$ DR. $\frac{1}{2}$ REAM THROUGH, $\frac{1}{32}$ CSINK, .79
12.7 13 HOLES




TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
 $\pm .0005$ DECIMAL
 $\pm \frac{1}{64}$ FRACTIONAL

DRAWN BY: E.F.S.

SCALE: _____

1-2-3 BLOCK (DUAL DIMENSIONING)

DWG. NO. 45.1



NOTES:
 MATL. C.R.S. SAE 1020
 BREAK ALL SHARPEGES.
 HARDEN AND TEMPER, FINISH GRIND TO 16 MICROINCHES.
 2 REQD. (MATCHED IN PAIRS)
 LEAVE .030 FOR GRINDING ON .500 AND
 .750 DIMENSIONS.

TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 ±.005 DECIMAL
 ± 1/64 FRACTIONAL
 ± 1° ANGULAR


DRAWN BY: E.F.S.

SCALE: ———

PARALLELS (INCHES)

DWG.NO. 50 A

8 DIA. 10 HOLES EQUALLY SPACED



NOTES:

MATL. CRS SAE 1020

BREAK ALL SHARP EDGES.

HARDEN AND TEMPER, FINISH GRIND TO 16 MICRONS.

2 REQD. (MATCHED IN PAIRS)

TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
± 0.4 MILLIMETER


DRAWN BY: V.C.L.

SCALE: —

PARALLELS (MILLIMETERS)

DWG.NO. 50 B

ITEM	PART NAME	MATL.
1	CLAMPING SCR	CRS
2	ADJUSTING SCR.	CRS
3	THREADED JAW	CRS
4	LOOSE JAW	CRS
5	STRAIGHT CLIP	CRS
6	RD. HD. MAGN. SCR 8-32 X $\frac{1}{2}$	COMM




DRAWN BY: V.C.L

PARALLEL CLAMP
ASSEMBLY

DWG. NO. 56

TOLERANCES:
(UNLESS OTHERWISE
SPECIFIED)
± .003 DECIMAL
± $\frac{1}{64}$ FRACTIONAL



MATERIAL: CRS
CASE HARDEN


REF. NO.	FINISHED DIMENSIONS (INCHES)										
	A	B	C	D	E	F	G	H	J	K, CBORE.	L
1	$\frac{1}{2}$	$\frac{3}{16}$	$\frac{5}{16}$	$\frac{5}{32}$	1	$\frac{3}{4}$	$\frac{1}{16}$	$\frac{1}{2}$	$\frac{1}{8}$ DIA X $\frac{5}{32}$ DEEP	$\frac{7}{32}$ DIA. $\frac{1}{4}$ X $\frac{3}{32}$ DEEP	6-32 UNC X $\frac{3}{16}$ DP.
2	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	1	$\frac{3}{32}$	$\frac{3}{4}$	$\frac{3}{16}$ DIA X $\frac{3}{16}$ DEEP	$\frac{9}{32}$ DIA. $\frac{5}{16}$ X $\frac{3}{32}$ DEEP	6-32 UNC X $\frac{3}{16}$ DP.
3	$\frac{3}{8}$	$\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{4}$	$\frac{1}{4}$ DIA X $\frac{1}{4}$ DEEP	$\frac{11}{32}$ DIA. $\frac{7}{16}$ X $\frac{3}{32}$ DEEP	8-32 UNC X $\frac{3}{16}$ DP.
4	4	$\frac{5}{8}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{5}{32}$	1	$\frac{5}{16}$ DIA X $\frac{5}{16}$ DEEP	$\frac{13}{32}$ DIA. $\frac{9}{16}$ X $\frac{3}{32}$ DEEP	8-32 UNC X $\frac{5}{16}$ DP.
5	5	$\frac{3}{4}$	$\frac{3}{4}$	$\frac{3}{8}$	$2\frac{3}{8}$	$1\frac{3}{4}$	$\frac{3}{16}$	1	$\frac{3}{8}$ DIA X $\frac{3}{8}$ DEEP	$\frac{17}{32}$ DIA. $\frac{11}{16}$ X $\frac{3}{32}$ DEEP	8-32 UNC X $\frac{5}{16}$ DP.

DRAWN BY: V.C.L.


PARALLEL CLAMP
LOOSE JAW (INCHES)

DWG. NO. 57 A

MATERIAL: CRS
CASE HARDEN



ALTERNATE JAW DESIGNS



REF. NO.	FINISHED DIMENSIONS											INCHES		
	MILLIMETERS													
	A	B	C	D	E	F	G	H	J	K,	CBORE.	L		
1	54	8	8	4.0	25.4	19.1	1.6	12.7	3.18D	X 3.97 DP	5.56D	6.35 X 2.38 DP	6-32 UNC x $\frac{3}{16}$ DP.	
2	69.9	9.5	9.6	4.8	31.8	25.4	2.4	19.1	4.76D	X 4.76 DP	7.15D	7.94 X 2.38 DP	6-32 UNC x $\frac{3}{16}$ DP.	
3	85.7	13	12.8	6.4	38.1	31.8	3.2	19.1	6.35D	X 6.35 DP	8.73D	11.11 X 2.38 DP	8-32 UNC x $\frac{5}{16}$ DP.	
4	101.6	16	15.8	7.9	44.5	38.1	4.0	25.4	7.94D	X 7.94 DP	10.32D	14.29 X 2.38 DP	8-32 UNC x $\frac{5}{16}$ DP.	
5	127	19	19	9.5	60.3	44.5	4.8	25.4	9.53D	X 9.53 DP	13.50D	17.46 X 2.38 DP	8-32 UNC x $\frac{5}{16}$ DP.	


TOLERANCES: UNLESS OTHERWISE SPECIFIED ± 0.076 MM.
FRACTIONAL: $\pm \frac{1}{64}$

DRAWN BY: V.C.L


PARALLEL CLAMP
LOOSE JAW (MILLIMETERS)

DWG. NO. 57B

H, TWO HOLES



ALTERNATE JAW DESIGNS



FINISHED DIMENSIONS (INCHES)

REF. NO.	A	B	C	D	E	F	G	H
1	$2\frac{1}{8}$	$\frac{5}{16}$	$\frac{5}{16}$	$\frac{3}{32}$	1	$\frac{3}{4}$	$\frac{1}{16}$	10-24UNC-2
2	$2\frac{3}{4}$	$\frac{3}{8}$	$\frac{3}{8}$	$\frac{1}{16}$	$1\frac{1}{4}$	1	$\frac{3}{32}$	$\frac{1}{4}$ -20UNC-2
3	$3\frac{3}{8}$	$\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{1}{4}$	$\frac{1}{8}$	$\frac{5}{16}$ -18UNC-2
4	4	$\frac{5}{8}$	$\frac{5}{8}$	$\frac{5}{16}$	$1\frac{3}{4}$	$1\frac{1}{2}$	$\frac{5}{32}$	$\frac{3}{8}$ -16UNC-2
5	5	$\frac{3}{4}$	$\frac{3}{4}$	$\frac{3}{8}$	$2\frac{3}{8}$	$1\frac{3}{4}$	$\frac{1}{8}$	$\frac{1}{2}$ -13UNC-2

TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)

$\pm .003$ DECIMAL

$\pm \frac{1}{64}$ FRACTIONAL


MATERIAL: CRS

CASE HARDEN

DRAWN BY: V.C.L.


PARALLEL CLAMP
THREADED JAW (INCHES)

DWG. NO. 58A



H, 2 HOLES

ALTERNATE JAW DESIGNS



REF. NO.	FINISHED DIMENSIONS							
	MILLIMETERS						INCHES	
	A	B	C	D	E	F	G	H
1	54	8.0	8.0	4.0	25.4	19.1	1.6	10-24UNC-2
2	69.9	9.5	9.6	4.8	31.8	25.4	2.4	1/4-20UNC-2
3	85.7	13.0	12.8	6.4	38.1	31.8	3.2	5/16-18 UNC-2
4	101.6	16.0	15.8	7.9	44.5	38.1	4.0	3/8-16 UNC-2
5	127.0	19.0	19.0	9.5	60.3	44.5	4.8	1/2-13 UNC-2


MATERIAL. CRS
CASE HARDEN

TOLERANCES: (UNLESS OTHERWISE SPECIFIED) ± 0.4 MM.

DRAWN BY: V.C.L

PARALLEL CLAMP
THREADED JAW (MILLIMETERS)

DWG. NO. 58B



NOTES: BREAK ALL SHARP EDGES.
MATERIAL: CRS


TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
± .003 DECIMAL
± 1/64 FRACTIONAL

REF. NO	FINISHED DIMENSIONS (INCHES)									
	A	B	C	D	E	F	G	H	J	
1	3/4	5/16	5/32	1/2	1/16	7/32	.149DIA.	7/64	1/8	1/32
2	1	3/8	3/16	3/4	1/16	9/32	.149DIA.	9/64	1/8	1/32
3	1 1/8	1/2	1/4	3/4	3/8	11/32	.177DIA.	11/64	1/8	1/16
4	1 3/8	5/8	5/16	1	1/8	13/32	.177DIA.	13/64	1/8	1/16
5	1 7/8	3/4	3/8	1 1/4	1/8	17/32	.177DIA.	17/64	1/8	1/16


DRAWN BY: V.C.L.

PARALLEL CLAMP
STRAIGHT CLIP

DWG. NO. 59



NOTES:
 FINISH ALL OVER.
 BREAK SHARP EDGES.
 TOLERANCES:
 (UNLESS OTHERWISE
 SPECIFIED)
 FRACTIONAL $\pm \frac{1}{64}$
 DECIMAL $\pm .003$



ALTERNATE DESIGNS FOR KNURLED END


REF. NO.	FINISHED DIMENSIONS (INCHES)											JAW OPENING
	A	B	C	D	E	F	G	H	J	K	L	
1	$\frac{5}{16}$	$2\frac{3}{32}$	$1\frac{1}{4}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{1}{4}$	$\frac{5}{32}$.120	$\frac{1}{8}$	$\frac{1}{32}$ R	10-24UNC-2	1
2	$\frac{3}{8}$	$2\frac{13}{16}$	$1\frac{3}{8}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{5}{16}$	$\frac{7}{32}$.180	$\frac{1}{8}$	$\frac{1}{32}$ R	$\frac{1}{2}$ -20UNC-2	$1\frac{1}{2}$
3	$\frac{1}{2}$	$3\frac{5}{8}$	$2\frac{3}{8}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{3}{8}$	$\frac{9}{32}$.240	$\frac{3}{16}$	$\frac{1}{16}$ R	$\frac{5}{16}$ -18UNC-2	2
4	$\frac{5}{8}$	$4\frac{1}{16}$	$2\frac{15}{16}$	1	$\frac{1}{2}$	$\frac{1}{2}$	$\frac{11}{32}$.300	$\frac{5}{16}$	$\frac{1}{16}$ R	$\frac{3}{8}$ -16UNC-2	$2\frac{1}{2}$
5	$\frac{3}{4}$	$5\frac{3}{4}$	4	$1\frac{1}{8}$	$\frac{9}{16}$	$\frac{5}{8}$	$\frac{7}{16}$.360	$\frac{1}{4}$	$\frac{1}{16}$ R	$\frac{1}{2}$ -13UNC-2	$3\frac{1}{2}$

MATERIAL: CRS CASE HARDEN

PARALLEL CLAMP
 CLAMPING SCREW

DRAWN BY: V.C.L.

DWG. NO. 60




NOTES:
 FINISH ALL OVER.
 BREAK SHARP EDGES.
 TOLERANCES:
 (UNLESS OTHERWISE SPECIFIED)
 FRACTIONAL $\pm \frac{1}{64}$

ALTERNATE DESIGNS FOR KNURLED END

REF. NO.	FINISHED DIMENSIONS (INCHES)										JAW OPENING
	A	B	C	D	E	F	G	H	J		
1	$\frac{5}{16}$	$2\frac{1}{4}$	$1\frac{3}{8}$	$\frac{5}{8}$	$\frac{1}{4}$	$\frac{7}{32}$	$\frac{1}{8}$	$\frac{3}{16}$ DIA.	10-24UNC-2		1
2	$\frac{3}{8}$	3	2	$\frac{3}{4}$	$\frac{5}{16}$	$\frac{9}{32}$	$\frac{1}{8}$	$\frac{1}{4}$ DIA.	$\frac{1}{4}$ -20UNC-2		$1\frac{1}{2}$
3	$1\frac{1}{2}$	$3\frac{7}{8}$	$2\frac{5}{8}$	$\frac{7}{8}$	$\frac{3}{8}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{5}{16}$ DIA.	$\frac{5}{16}$ -18UNC-2		2
4	$\frac{5}{8}$	$4\frac{3}{4}$	$3\frac{1}{4}$	1	$\frac{7}{16}$	$\frac{1}{2}$	$\frac{3}{16}$	$\frac{3}{8}$ DIA.	$\frac{3}{8}$ -16UNC-2		$2\frac{1}{2}$
5	$\frac{3}{4}$	$6\frac{1}{8}$	$4\frac{3}{8}$	$1\frac{1}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{1}{4}$	$\frac{1}{2}$ DIA.	$\frac{1}{2}$ -13UNC-2		$3\frac{1}{2}$

MATERIAL: C R S
 CASE HARDEN

DRAWN BY: V.C.L.	PARALLEL CLAMP ADJUSTING SCREW	DWG. NO. 61



NOTES:
MATT. CAST IRON
I REQD.

TOLERANCES:
(UNLESS OTHERWISE SPECIFIED)
±.0005 DECIMAL

DRAWN BY: E.F.S.
SCALE: ———

MOTOR PLATE

DWG. NO. 72